



The DZ Company, LLC  
4321 W. Eisenhower Blvd.  
Loveland, CO 80537  
970-667-2254

**Sienna Construction Note**  
6/27/10

Under-rated capacitor on 100W amp board

**Problem:** When using the 100W amp under conditions of high VSWR, capacitors C23 and/or C24 can burn up.

**Solution:** Replace C23 and C24 with .01uF to .1uF 500V disk ceramic capacitors. These capacitors tend to be large, so be sure to press them down so they do not extend more than 0.4" above the top of the board.